

ERA25FA119

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of main wreckage. (NTSB)



Photograph 2 - View of fragmented wreckage pieces scattered throughout site. (NTSB)



Photograph 3 - View of fuselage wrapped around palmetto trees. (NTSB)



Photograph 4 - View of fragmented wreckage in swamp. (NTSB)



Photograph 5 - View of right wing looking towards fuselage during wreckage layout. (NTSB)



Photograph 6 - View of damaged propeller blade. (NTSB)



Photograph 7 - View of impact damaged engine after recovery. (NTSB)



Photograph 8 - View of impact damaged engine compressor section. (NTSB)



Photograph 9 - Closeup view of damaged compressor blades and stator airfoils. (NTSB)