

ERA25FA185

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage



Photograph 2 - Main Wreckage



Photograph 3 - Main Wreckage



Photograph 4 - Close up of washer impression on plug



Photograph 5 - Close up of screw impression on plug