

ERA25LA006

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage (Courtesy of FAA)



Photograph 2 - Right Wing Damage (Courtesy of FAA)



Photograph 3 - Right Wing Damage (Courtesy of FAA)