

ERA25LA015

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - FAA Digital Photograph. Right Side View of the Airplane At the Accident Site.
Note the Large Tree Contact to the Leading Edge Near the Wing Root**



Photograph 2 - FAA Digital Photograph. Right Forward Quartering View of the Airplane At the Accident Site



Photograph 3 - FAA Digital Photograph Left Side View of the Airplane At the Accident Site



Photograph 4 - FAA Digital Photograph. Right Rear Quartering View of the Airplane At the Accident Site



Photograph 5 - FAA Digital Photograph Aft View of the Tailwheel Assembly and Portions of Both Horizontal Stabilizers, Elevators, and Aft Empennage