


ERA25LA019

INVESTIGATION PHOTOGRAPHS




Photograph 1 - N11519 on Runway 05 at Lee Gilmer Memorial Airport (Courtesy of Gainesville PD)



Photograph 2 - N11519 on Runway 05 at Lee Gilmer Memorial Airport (Courtesy of Gainesville PD)



Photograph 3 - Substantial Damage to Engine Mount and Forward Fuselage Structure (Courtesy of FAA)



Photograph 4 - Cockpit Floor Area with Residue from Discharged Fire Extinguisher (Courtesy of FAA)