

ERA25LA026

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Side View of Right Wing Damage (Courtesy of FAA)



Photograph 2 - Right Side View of Right Wing Damage (Courtesy of FAA)



Photograph 3 - Closeup View of Right Wing Damage (Courtesy of FAA)