

ERA25LA027

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Helicopter on Scene (Courtesy of FAA)



Photograph 2 - Damage to the Pitch Control Link (Courtesy of FAA)



Photograph 3 - Damaged Pitch Control Link (Courtesy of FAA)