

ERA25LA035

INVESTIGATIVE PHOTOS



Photograph 1 - Main wreckage, front view (Courtesy of FAA)



Photograph 2 - main wreckage, left side view (Courtesy of FAA)



Photograph 3 - Fuel Selector Valve (Courtesy of FAA)