

ERA25LA036

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Airplane (Courtesy of FAA)



Photograph 2 - Rear View of Airplane (Courtesy of FAA)



Photograph 3 - Left Side View of Airplane (Courtesy of FAA)



Photograph 4 - Fuselage Damage on Left Side of Airplane (Courtesy of FAA)



Photograph 5 - Right Side View of Vertical Stabilizer and Rudder (Courtesy of FAA)