

ERA25LA040

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damaged helicopter and separated tail boom. (Courtesy of Operator)



Photograph 2 - Closeup view of damaged helicopter. (Courtesy of Operator)



Photograph 3 - View of aerial tree trimming saw and right of way. (Courtesy of Operator)