

ERA25LA053

ON SCENE PHOTOGRAPHS



Photograph 1 - Wreckage overview (Source: FAA)



Photograph 2 - Wreckage overview (Source: FAA)



Photograph 3 - Wreckage overview (Source: FAA)



Photograph 4 - Ground scar looking toward the wreckage site (Source: FAA)



Photograph 5 - Image of ground scars on the tarmac (looking toward runway) (Source: FAA)



Photograph 6 - Cockpit image with fuel selector visible in the "LEFT" position (Source: FAA)