

Lucas Winn
Aviation Accident Investigator
Aviation Safety, Eastern region

Date: December 3, 2024

Subject: ERA25LA054, Aircraft inspection Times

The Following airframe and engine times for Bakeng Duce , N72WJ, were extracted from a photo of the last page of the aircraft Maintenance Logs provided by the pilot:

Last Inspection: Condition, 6/7/2024

AFTT: 205.1 SMOH: 60.7 Time Type: Tach

Pilot	REMARKS
5/1/2024 [REDACTED]	Tach 42.4 Total Airframe Time 186.8 SMOH 42.4
Spot Cool, Replaced; Cylinder Section Fuel (8 master 12 center)	I certify that this Airframe has been inspected IAW an Annual Condition Inspection and found to be in an Airworthy condition and safe for flight.
11/1/2024 Time since discharge 15cm	6/7/2024 Tach 60.7 Tach 60.7 Total Airframe Time 205.1 SMOH 60.7
Annual Condition Inspection for Flight IAW for 43 and N320	I certify that this Airframe has been inspected IAW scope & detail of FAR 43 App D for annual conditional inspection & found to be in an airworthy condition.
10/1/2024 1-100 Look OK good	