

ERA25LA056

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aircraft On-Scene (Courtesy of Pilot)



Photograph 2 - Damage to Fuselage (Courtesy of Pilot)



Photograph 3 - Crack in Battery Bridge (Courtesy of Pilot)



Photograph 4 - Crack in Battery Bridge (Courtesy of Pilot)