

ERA25LA059

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Close-up view of helicopter hull showing skid damage
(Courtesy of FAA)**



**Photograph 2 - Close-up rear view of helicopter hull damage
(Courtesy of FAA)**



**Photograph 3 - Left side view of helicopter showing landing skid damage
(Courtesy of FAA)**