

ERA25LA060

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Tug collision with elevator (Courtesy of FAA)



Photograph 2 - Skin deformation noted to elevator (Courtesy of FAA)



Photograph 3 - Damage noted to tug's windshield (Courtesy of FAA)