

ERA25LA064

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site (Courtesy of FAA)



Photograph 2 - Fractured airframe (NTSB)



Photograph 3 - Fractured left wing (NTSB)



Photograph 4 - Fractured right wing (NTSB)



Photograph 5 - Impact separated horizontal stabilizer (NTSB)