

ERA25LA067

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane, postaccident (Courtesy of airplane owner)**



**Photograph 2 - Right side tail and horizontal stabilizer accident damage  
(Courtesy of airplane owner)**



**Photograph 3 - Right side tail accident damage  
(Courtesy of airplane owner)**



**Photograph 4 - bottom right horizontal stabilizer accident damage  
(Courtesy of airplane owner)**