

ERA25LA077

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of Pilot)



Photograph 2 - Forward left fuselage accident damage (Courtesy of FAA)



Photograph 3 - Right wing accident damage (Courtesy of FAA)



Photograph 4 - Left wing accident damage (Courtesy of FAA)