

ERA25LA079

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at the accident site. (Courtesy of FAA)



Photograph 2 - View of the airplane at the accident site. (Courtesy of FAA)



Photograph 3 - View of the rudder at the accident site. (Courtesy of FAA)



Photograph 4 - View of damage to the left wing. (Courtesy of FAA)