

ERA25LA083

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of airplane on runway (Courtesy of FAA)



Photograph 2 - Fuselage damage (Courtesy of FAA)



Photograph 3 - Fuselage damage (Courtesy of FAA)