

ERA25LA084

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overview of the Damage to the Airplane (Courtesy of Melbourne PD)



Photograph 2 - View of the Damage to the Left Side of the Airplane (Courtesy of Melbourne PD)



Photograph 3 - Right Side Damage and Cut Power Line (Courtesy of Melbourne PD)



Photograph 4 - Right Wing Damage (Courtesy FAA)



Photograph 5 - Left Wing Damage (Courtesy FAA)



Photograph 6 - Left Wing As Found (Courtesy FAA)



Photograph 7 - Repaired Wire in Relation to the Airplane (Courtesy FAA)