

ERA25LA090

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of Virginia State Police)



Photograph 2 - Nose landing gear damage (Courtesy of FAA)



Photograph 3 - Left side fuselage damage (Courtesy of FAA)



Photograph 4 - Aft belly damage (Courtesy of Pilot)



Photograph 5 - Separated nose wheel with partial fork (Courtesy of Pilot)