

ERA25LA092

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane postaccident (Courtesy of FAA)**



**Photograph 2 - Lower right wing damage of the high wing airplane (Courtesy of FAA)**



**Photograph 3 - Upper right wing and aileron damage to the high wing airplane (Courtesy of FAA)**