

ERA25LA097

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of FAA)



Photograph 2 - Forward right fuselage accident damage (Courtesy of FAA)



Photograph 3 - Left side wing strut accident damage, fwd and aft (Courtesy of FAA)



Photograph 4 - Left side fuselage accident damage (Courtesy of FAA)