

ERA25LA111

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. Frontal View of the Airplane At the Accident Site



Photograph 2 - FAA Digital Photograph. Left Forward Quartering View of the Airplane at the Accident Site



Photograph 3 - FAA Digital Photograph. Right Side View of the Airplane at the Accident Site



Photograph 4 - FAA Digital Photograph. View Showing the Ground Path of the Airplane



Photograph 5 - FAA Digital Photograph. View of a portion of the Right Wing. Note Dirt on the Leading Edge on Top of a Layer of Ice



Photograph 6 - FAA Digital Photograph. Frontal View of the Outer Section of the Right Wing Showing Substantial Damage