

ERA25LA112

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of FAA)



Photograph 2 - Right wing accident damage (Courtesy of FAA)



Photograph 3 - Right horizontal stabilizer and elevator accident damage (Courtesy of FAA)



Photograph 4 - Left wing accident damage (Courtesy of FAA)



Photograph 5 - Forward fuselage accident damage (Courtesy of FAA)