

ERA25LA115

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Wing Accident Damage (Courtesy of Pilot)



Photograph 2 - Right Wing Accident Damage (Courtesy of Pilot)



Photograph 3 - Fuselage Accident Damage (Courtesy of Pilot)