


ERA25LA118

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane with Collapsed Nose Gear (Courtesy of FAA)



Photograph 2 - Damaged Runway Light (Courtesy of FAA)



Photograph 3 - Firewall Damage (Courtesy of FAA)



Photograph 4 - Damage Behind Firewall (Courtesy of FAA)