

ERA25LA121

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Airplane Damage (Courtesy of C. Blas)



Photograph 2 - Damage to Airport Truck (Courtesy of C. Blas)



Photograph 3 - Broken Airplane Engine Mount (Courtesy of C. Blas)