

ERA25LA128

INVESTIGATION PHOTOGRAPHS



Photograph 1 – White airplane with blue and red stripes resting on snowbank
(Courtesy of FAA)



Photograph 2 –Front view of white airplane with blue and red stripes resting on snowbank
(Courtesy of FAA)



Photograph 3 – View of right wing of airplane showing buckling damage
(Courtesy of FAA)