

ERA25LA129

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to main rotor (Courtesy of FAA)



Photograph 2 - Damage to helicopter (Courtesy of FAA)