

ERA25LA131

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Pre accident view of airplane. (Courtesy of FAA)



Photograph 2 - View of airplane on runway with landing gear up. (Courtesy of FAA)



Photograph 3 - View of damaged fuselage. (Courtesy of FAA)