

ERA25LA133

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Postaccident (Courtesy of Airport Ops)



Photograph 2 - Pedestal structure accident damage (Courtesy of FAA)



Photograph 3 - Lower vertical stabilizer accident damage (Courtesy of Flight School)



Photograph 4 - Firewall structure accident damage (Courtesy of FAA)