

ERA25LA156

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Left Side Fuselage Damage (Courtesy of FAA)



Photograph 3 - Right Side Fuselage Damage (Courtesy of FAA)



Photograph 4 - Closeup of Right Side Fuselage Damage (Courtesy of FAA)



Photograph 5 - Vertical Fin Damage (Courtesy of FAA)