

ERA25LA161

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rear View of Airplane at Accident Site (Courtesy of Virginia State Police)



Photograph 2 - Right Side View of Airplane at Accident Site (Courtesy of Virginia State Police)



Photograph 3 - Front View of Airplane at Accident Site (Courtesy of Virginia State Police)