



Photo 1 – View of Airplane as Found (FAA)



Photo 2 – View of Airplane Left Fuselage and Inboard Left Wing (FAA)



Photo 3 – View of Damage to Inboard Right Wing (FAA)



Photo 4 – View of Left Fuel Tank Contents (FAA)



Photo 5 - View of Right Fuel Tank Contents (FAA)