

ERA25LA172

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Right Side View of Main Wreckage (Courtesy of FAA)




Photograph 3 - Left Side View of Main Wreckage (Courtesy of FAA)



Photograph 4 - left Side of Fuselage (Courtesy of Piper Aircraft)



Photograph 5 - Right Side of Fuselage (Courtesy of Piper Aircraft)



Photograph 6 - Throttle Quadrant and Flap Handle (Courtesy of Piper Aircraft)



Photograph 7 - Landing Gear Handle (Courtesy of Piper Aircraft)