

ERA25LA189

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Main Wreckage (Courtesy of FAA)




Photograph 2 - Main Wreckage Close-up [Carburetor Heat Control] (Courtesy of FAA)



Photograph 3 - Carburetor Heat Control (Courtesy of Lycoming)




Photograph 4 - Engine (Courtesy of Lycoming)




Photograph 5 - Top Spark Plugs (Courtesy of Lycoming)



Photograph 6 - Carburetor Heat Valve (Courtesy of Lycoming)



Photograph 7 - Carburetor Bowl (Courtesy of Lycoming)



Photograph 8 - Carburetor Floats (Courtesy of Lycoming)



Photograph 9 - Gascolator (Courtesy of Lycoming)