

ERA25LA196

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site (Courtesy of FAA)



Photograph 2 - Rear view photo of Airplane at Accident Site (Courtesy of FAA)