

ERA25LA197

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the Airplane with Damage to Left Wing (Courtesy of FAA)



Photograph 2 - View of the Nose Hull Damage (Courtesy of FAA)