

ERA25LA199

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the accident site. (Courtesy of FAA)



Photograph 2 - View of damage to the left wing. (Courtesy of FAA)



Photograph 3 - View of damage to the fuselage. (Courtesy of FAA)