

ERA25LA205

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane overview (gear extended) (Courtesy of FAA)



Photograph 2 - Damage to fuselage (Courtesy of FAA)



Photograph 3 - Damage to fuselage (Courtesy of FAA)