

ERA25LA207

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident with damaged wing struts (Courtesy of flight school)



Photograph 2 - Wing strut accident damage (Courtesy of flight school)



Photograph 3 - Wing strut attach fitting accident damage (Courtesy of flight school)