

ERA25LA208

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wing Displacement and Damage (Courtesy of FAA)



Photograph 2 - Fuselage Damage (Courtesy of FAA)