

ERA25LA221

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage structure left wing deformation (Courtesy of FAA)



Photograph 2 - Deformation noted to the left wing (Courtesy of FAA)