

ERA25LA233

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. Frontal View of a Portion of the Left Wing Showing the Leading Edge Impact Damage



**Photograph 2 - FAA Digital Photograph. View of the Bottom of a Portion of the Left Wing.
Arrow Points to Buckling of the Lower Wing Skin Aft of the Main Spar**



Photograph 3 - FAA Digital Photograph. View Showing the Approximate 48 Inches of Span Damage to the Leading Edge