

ERA25LA236

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of airplane with blue and red stripes in a field.
(Courtesy of FAA)**



**Photograph 2 - View of right main landing gear damage.
(Courtesy of FAA)**



**Photograph 3 - View of missing #1 propeller out of propeller hub.
(Courtesy of FAA)**



**Photograph 4 - View of #2 propeller missing from propeller hub.
(Courtesy of FAA)**



**Photograph 5 - View of #3 propeller still connected to hub.
(Courtesy of FAA)**