

ERA25LA240

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Accident site from the air (Courtesy of Law Enforcement)**



**Photograph 3 - Helicopter postaccident (Courtesy of Law Enforcement)**



**Photograph 4 - Fuselage accident damage (Courtesy of FAA)**



**Photograph 6 - Rotor mast damage (Courtesy of NTSB)**