

ERA25LA244

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Front view of Aircraft (Courtesy of FAA)



Photograph 2 - Right side of aircraft (Courtesy of FAA)



Photograph 3 - Left side of aircraft (Courtesy of FAA)



Photograph 4 - Close up of damage to right side of fuselage (Courtesy of FAA)



Photograph 5 - Close up of damage to left side of fuselage (Courtesy of FAA)



Photograph 6 - Damage to lower firewall and supporting structure (Courtesy of FAA)



Photograph 7 - Nose wheel showing no rim damage (Courtesy of FAA)