

ERA25LA245

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right wing damage. (Courtesy of Pilot)



Photograph 2 - View of fuselage damage. (Courtesy of Pilot)



Photograph 3 - View of left wing, right wing, and fuselage damage. (Courtesy of Pilot)